


99XA-081

:HUB ADAPTER ASSEMBLY / ASSEMBLAGE
ADAPTEUR MOYEU



Liste des pièces / Part List			
REF	#pièce/part	QTÉ/QTY	Couple / Torque
1	04AM-029	2	
2	HSFCS3/8-16x1,25B2L	8	
3	04AM-058	2	
4	04AM-064	2	
5	04AM-065	4	
6	HNWM10-1,25	16	66 N-m / 49 Lbs*feet

2011-07-21



Les Fabrication TJD inc.

147, chemin des Raymond Rivière-du-Loup (Québec), G5R 5X9
www.tjd.ca