


99XA-056

:HUB ADAPTER ASSEMBLY / ASSEMBLAGE  
ADAPTEUR MOYEU

## Liste des pièces / Part List

REF	#pièce/part	QTÉ/QTY	Couple / Torque
1	04AM-025	4	
2	00AM-005	2	
3	04AM-019	2	
4	04AM-016	2	
5	HNWM10-1,25	8	66 N-m / 49 Lbs*feet
6	HFNM10x1,25G8,8	8	66 N-m / 49 Lbs*feet
7	HNW7116-20NF	8	75N-m / 55 Lbs*feet

2011-07-21



Les Fabrication TJD inc.

147, chemin des Raymond Rivière-du-Loup (Québec), G5R 5X9  
www.tjd.ca